ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0893	NA	Houses
Segment No.	**Total Length (m)**	
9/S-W0893/S054109	121.06	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	121.06	77.565797	13.057821	77.565240	13.057104	Doddabommasandra Main Road	Dead end

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Repairs to Culverts, Drains and Desilting of Drains, Missing Covering Slabs at Virupakshapura, Kodigehalli in Ward No. 09 (Vidyaranyapura).	3000000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Asphalting to Roads and Improvements to Drains by using solid block to rise the drain and providing covering slab	009-20-000094
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/189/2020-21	10/02/2021	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
02/03/2022	01/03/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Bharath. S		0.00
Phone No.	**E-Mail ID**	
9591904500		

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0893

Date: 23/08/2022 Time: 12:29:14 RH 20220823122914 Page 1 of 2

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhath Bangaluru Mahanagara Palike

Field Inspection Details

Number of Trees

0

Any Other Information

Name

somadhekar g l

Date of Inspection

27/06/2022

Remarks

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	11/07/2022	27/07/2022	As proposed
SE	G R Devendra Naik	29/06/2022	27/07/2022	Forwarded
EE	Pradeep B N	27/06/2022	27/07/2022	Forward
AEE	Shivakumar M Goudar	27/06/2022	27/07/2022	Verified
AE	Somashekar G L	27/06/2022	27/07/2022	Mobile Verification Done
AE	Somashekar G L	27/06/2022	27/07/2022	Forward

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0494	NA	Maramma Temple
Segment No.	**Total Length (m)**	
9/S-W0494/S053702	118.67	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	118.67	77.573450	13.064997	77.572372	13.065181	Virupakshapura Main Road	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Repairs to Culverts, Drains and Desilting of Drains, Missing Covering Slabs at Virupakshapura, Kodigehalli in Ward No. 09 (Vidyaranyapura).	3000000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Drains by using solid block to rise the drain and providing covering slab	009-20-000094
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/189/2020-21	10/02/2021	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
02/03/2022	01/03/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Bharath. S		0.00
Phone No.	**E-Mail ID**	
9591904500		

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhat Bangalore Mahanagara Palike

Field Inspection Details

Number of Trees

0

Date of Inspection

27/06/2022

Any Other Information

Remarks

Name

somadhekar g l

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	11/07/2022	27/07/2022	As proposed
SE	G R Devendra Naik	29/06/2022	27/07/2022	Forwarded
EE	Pradeep B N	27/06/2022	27/07/2022	Forward
AEE	Shivakumar M Goudar	27/06/2022	27/07/2022	Verified
AE	Somashekar G L	27/06/2022	27/07/2022	Mobile Verification Done
AE	Somashekar G L	27/06/2022	27/07/2022	Forward